

# Mitchell Diagnostics™ Reports | Custom Format

Designed to Support Collision Repair and Claims Workflow

Clearly Identified as Pre or Post-Scan  
With Date/Time Stamp

Tool Identifier With  
Software Version

Confirms That the Tool  
Found the Vin and It Was  
Not Manually Entered

Pre-Scan Codes Help  
Ensure Proper Parts  
Order and Accurate  
Delivery Date Forecast

Mitchell Diagnostics   Post-Scan Report		SCRUMPTIOUS RC2	
Post-Scan on 2/11/2020 5:20:20 PM MST		9341 Boulevard Sainte-Anne, Sainte-Anne-de-Beaupré, QC G0A 3C0	
Tool ID: AaromICA		Office: (555) 555-5555	
Scan ID: Test_BH_M02		SCRUMPTIOUS@mitchell.com	
<b>2016 Jeep Cherokee Limited 3.2</b>			
VIN		RO #	
1C4PJMB59HW552543 <i>Verified</i>		234	
<b>System Summary</b>		<b>DTC Summary</b>	
29 Total Controllers Scanned		13 Current Code Types	
5 Controllers w/ DTCs		4 Pending Code Types	
17 Controllers w/ No DTCs		6 History Code Types	
7 Unread Controllers		0 Other Code Types	
<b>Controllers W/ Diagnostic Trouble Codes (5)</b>			
<b>ENGINE</b>			
DTC		Current	Pending History
P0010-00	Camshaft Position Actuator Solenoid Control Circuit		✓
B0020-1A	Decreased resistance in the driver's side airbag inflator	✓	✓
B00C2-16	Internal failure of the front passenger's weight sensor (rear inner side)	✓	✓
P2195 (48)	Air Fuel Ratio (AF) Sensor (Sensor 1) Signal Stuck Lean	✓	✓ ✓
C1AA6	Yaw Rate Sensor Zero Point Malfunction	✓	✓

Vehicle Data

Categorized Summary  
of DTCs

DTC Details

To learn more, call 1.800.238.9111  
or visit [mitchell.com](http://mitchell.com).